




31103413500 Result 1 - 3 of 3

Article number	Description	Article status	Quantity
<input type="checkbox"/> 37466 01	 <p>LEMFÖRDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 3 413 500) Packing unit: 1 Quantity per packing unit: 1</p>	Normal	1
<input type="checkbox"/> 38117 01	 <p>LEMFÖRDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 3 413 500) Packing unit: 1 Quantity per packing unit: 1</p>	Normal	1
<input type="checkbox"/> 38643 01	 <p>LEMFÖRDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 3 413 500) Packing unit: 1 Quantity per packing unit: 1</p>	Normal	1

Article criteria

Article status: Please select...

IAM criteria:









Fitting Position:

- All
- Front (1)
- Front Axle (2)
- Front Axle Left (1)
- Front Axle Right (1)
- Lower (1)
- both sides (2)

for article number:

- All
- 27167 02 (1)
- 31178 01 (1)
- 31179 01 (1)
- 36306 01 (1)
- 36307 01 (1)
- 42652 01 (1)

31106768936 Result 1 - 4 of 4

Article number	Description	Article status	Quantity
<input type="checkbox"/> 38903 01	 <p>LEMFORDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 6 768 936) Packing unit: 1 Quantity per packing unit: 1</p>	no longer deliverable by the manufacturer	1 
<input type="checkbox"/> 38904 01	 <p>LEMFORDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 6 768 936) Packing unit: 1 Quantity per packing unit: 1</p>	no longer deliverable by the manufacturer	1 
<input type="checkbox"/> 42402 01	 <p>LEMFORDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 6 768 936) Packing unit: 1 Quantity per packing unit: 1</p>	Normal	1 
<input type="checkbox"/> 42408 01	 <p>LEMFORDER Service Pack Repair Kit, wheel suspension Found via OE number (31 10 6 768 936) Packing unit: 1 Quantity per packing unit: 1</p>	Normal	1 

Article criteria

Article status: Please select ...

IAM criteria: All, Front Axle Left (4), Front Axle Right (4)

Fitting Position: All, 27001 01 (2), 31211 01 (2)

for article number: All, 27001 01 (2), 31211 01 (2)